

Site Inspection Report

Inspection Date(s) 2/28/90

Site Name O'Henry Dry Cleaner

Site Address East Highway 38

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

Caroline Kwan - EPA
Bryce Rhymen - DPR

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

104(e) reinspection

Findings, Accomplishments, and Results:

Closed system - observed personnel
pulling overgrown plant from
discharge pipes -

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State officials, PRPs, or contractor regarding problems, schedule for resolution, etc.)

Distribution:

259837

